




OK-385

Four Station Heat Transfer Press

16"x20" 20" x 25"



- Four work stations – two working surface loads while the other two presses
- Air operated heated head movement for increased productivity
- Simple operation requiring little physical effort
- No need to slide trays back and forth
- Precision electronic temperature controller with digital display to prevent any temperature inconsistencies
- Timer with duty cycles of 1/10th of a second durations for consistency and quality of work

Platen Size
Platen Force
Electrical
Air Supply

16" x 20"
63 lbs psi
10.5 kW 240V 1PH
100 psi 1 cfm

20" x 25"
40 lbs psi
10.5 kW 240V 1PH
100 psi 1 cfm

Interchangeable Platens

4in x 4in	7in Round
6in x 10in	8in x 10in
6in x 20in	11in x 15in
7in Round	Double 3 in x 20 in

Custom shape & size
(must be smaller than heat platen size)